



S-TYPE	Date 07/99	S206-01
TECHNICAL BULLETIN		

Subject BRAKE PEDAL SWITCHES	Model S-TYPE Year 1999.25 MY VIN L00600 ON
--	---

ISSUE

From VIN L06314 a revised pattern of brake switch has been fitted in production. Owing to a modification that allows greater travel of the plunger, the appropriate fitting procedure, as detailed below, should be followed.

ACTION

The following procedures apply: Fitting procedure below.

1. Up to VIN L06313

Non Speed Control Vehicles

Where the brake switch is faulty, replace it with one of later specification.

Speed Control Vehicles

Where the brake switch (grey casing) is faulty, replace it with one of later specification.

Where the speed control de-activation switch (blue casing) is faulty, replace the switch (**no change in specification**) together with a replacement brake switch.

2. After VIN L06313

All Vehicles - with or without Speed Control.

It is only necessary to replace the faulty switch, but the new fitting procedure **must** be followed.

Fitting Procedure

1. Remove the faulty switch (or both switches where the speed control de-activation switch is faulty on vehicles prior to VIN L06313).
2. Press the brake pedal downwards as far as possible and hold it in this position.
The Jaguar Brake Pedal Holding Tool JDS 9013, part of the Jaguar Special Equipment, Brake System Power Hydraulic Test Kit, may be used for this purpose.
Similar proprietary tools are also available from other suppliers.
3. Fit the new switch with the pedal held in the 'down' position.
4. Unlock the safety catch on the switch by rotating the tag on the rear of the switch.
5. Release the brake pedal and allow the brake pedal to come to rest. As this occurs, the switch plunger will ratchet inwards.
6. Pull the brake pedal carefully upwards until **one** click is heard, then release the pedal.
7. Check for correct operation of the switch.

PARTS INFORMATION:

The following should be ordered via Jaguar Parts Operations, where required:

DESCRIPTION	OLD PART No.	NEW PART No.
Speed Control De-activation Switch	XR8 1616	Same
Brake Switch	XR8 1172	C2C 1074

WARRANTY INFORMATION:

Warranty Fault Codes:	BL-BJ-**	Speed Control De-activation Switch -	
	QN-FB-**	Brake Light Switch -	
SRO:	86-65-51	0.15 hours	Replace Brake Light Switch
	19-75-20	0.15 hours	Replace Speed De-activation Switch
	86-65-52	0.20 hours	Replace BOTH above switches.

Claims must be submitted in accordance with the current Jaguar Warranty Policy and Procedures Manual and its amendments.