



S-TYPE	Date 08/2001	S960-04
TECHNICAL BULLETIN		
Subject AMENDED REPAIR TIMES		Model ALL Year VIN

960 – Administrative Items

ISSUE: S960-04 - AMENDED REPAIR TIMES

This Technical Bulletin has been issued to inform Dealers of an amendment to the repair times for engine knock sensor renew, engine knock sensor – engine set renew, exhaust manifold – vehicle set renew.

ACTION

All dealers should update their records to include the following amendments to the labor time allowances:

Description	Engine Type	SRO	Original Labor Time Allowance	New Labor Time Allowance
Engine Front Knock Sensor - Renew	3.0 L	18 30 67	1.3 hours	2.3 hours
Engine Knock Sensor- Engine Set - Renew	3.0 L	18 30 69	1.6 hours	2.8 hours
Exhaust Manifold - Vehicle Set - Renew	4.0 L	30 15 57	1.4 hours	1.5 hours

Note: All labor time allowances are now shown to one decimal place.