



TECHNICAL BULLETIN

S501-16v3

12/2003

Subject

Sliding Roof Loss of Calibration

Model: S-TYPE

Year: 2002

VIN M45256 to M47040

Section: 501

Body Systems

Sub-Section: 501-17

Roof Opening Panel

Summary

S501-16v3: This Technical Bulletin has been issued due to customer complaints that the sliding roof may not shut properly and 'bounces' open when the closed position is reached. Symptoms can become apparent if the ignition is switched off when the sliding roof is in motion.

The information quoted in Technical Bulletin S501-16 has been superseded by that given in S501-21. Please destroy all copies of S501-16v2 and replace it with this Technical bulletin S501-16v3.