



TECHNICAL BULLETIN

S307-08

05/2002

Subject

TRANSMISSION SHIFT CABLE REPLACEMENT FOR INFORMATION ONLY

Model: S-TYPE Automatic Transmission Vehicles Only

Year: 1999 to 2001

VIN L00001 to M45255

Section: 307

Automatic Transmission System

Sub-Section: 307-05

**Automatic Transmission/Transaxle External
Controls**

Summary

A durability issue concerning the S-TYPE automatic transmission shift cable has been identified. Two problems have been identified that can lead to difficult gear selection, or inability to start the vehicle.

These problems are:

- The inner transmission shift cable movement is restricted/stiff.
- The outer transmission shift cable appears to be moving within the crimped ends.

Action

An improved cable that was fitted to later vehicles has resulted in cessation of customer complaints. Install new improved cable, available under existing part number (XR8 33366).