



S-TYPE	Date 04 / 99	S 501 - 01
---------------	------------------------	-------------------

TECHNICAL BULLETIN

Subject FRONT SEATS HANDLING PRECAUTIONS	Model S-TYPE Year 1999.25 ONWARDS VIN L00600 ONWARDS
--	--


ISSUE:

This Technical Bulletin provides guidance on Handling Precautions when working on front seats.

ACTION:

Particularly where 'memory' seats are installed, care must be taken that damage is not caused to the flexible drive shaft and potentiometer of the seat fore/aft adjustment mechanism should it be necessary to remove a seat from the vehicle.

The flexible drive and potentiometer are located on the underside of the cushion pan, towards the front. While there is adequate clearance to handle the seat at the lower front edge of the cushion pan, care must nevertheless be exercised NOT to lift the seat by the shaft shown arrowed in the illustration below.



WARRANTY INFORMATION:

This Technical Bulletin is issued "For Information" only.