



<b>S-TYPE</b>	Date <b>07/2001</b>	<b>S960-03</b>
<b>TECHNICAL BULLETIN</b>		

Subject <b>AMENDED REPAIR OPERATION TIMES</b>	Model S-TYPE Year All VIN
--	---------------------------------

## 960-ADMINISTRATION

### ISSUE: S960-03 AMENDED REPAIR OPERATION TIMES

This Technical Bulletin has been issued to inform Dealers of an amendment to the repair times for the reverse park control sensors fitted to S-TYPE vehicles.

### ACTION

All Dealers should update their records to include the following amendments to the labor time allowances:

Description	SRO	Original Labor Time Allowance	New Labor Time Allowance
Reverse park control sensor – renew	86 62 01	0.9 Hours	1.2 Hours
Reverse park control sensor – vehicle set - renew	86 62 04	1.1 Hours	1.4 Hours

**Note: All labor time allowances are now shown to one decimal place.**