

Subject
WASHER PUMP CIRCUIT PROTECTION FUSE RATING UPGRADE
Model: S-TYPE
Year: 1999MY to 2000MY
VIN from L00001 to L86901
Section: 501
Body Systems
Sub-Section: 501-16
Wipers and Washers
Summary


S501-13: This Technical Bulletin has been issued due to customer complaints of the windscreen washer system becoming inoperative after attempting to operate the system when frozen.

Action

Due to the windscreen washer system becoming inoperative once activated when frozen (in cold weather), the washer pump circuit protection fuse should be up-rated from a 10amp fuse to a 15amp fuse. On a customer complaint basis only, follow the workshop procedure outlined below.

Workshop Procedure

- 1 Open hood and fit fender protectors.
- 2 Remove engine compartment fuse box cover.
- 3 Remove windscreen washer pump fuse (10amp, position 2).
- 4 Install up-rated windscreen washer pump fuse (15amp, position 2). (See Fig. 1)


Fig. 1

- 5 Install engine compartment fuse box cover.
- 6 Remove fender protectors and close hood.

Parts Information

The following parts must be ordered via Jaguar Cars Parts Operations.

Description	Part Number	Quantity
15amp mini fuse (blue)	JLM 20896	1

Warranty Information

Description	SRO	Labor Time Allowance	Warranty Code
Install washer pump fuse	10 10 99	0.2 Hours	KC-DB-01