



TECHNICAL BULLETIN

S205-02

10/2002

Subject

REAR DRIVE HALFSHAFT REPLACEMENT

Model: S-TYPE 2.5L Normally Aspirated (N/A)

Year: 2002.5

VIN M45255 to M72672

Model: S-TYPE 3.0L and 4.2L Normally Aspirated (N/A)

Year: 2002.5

VIN M45255 to M72472

Section: 205

Driveline System

Sub-Section: 205-05

Rear Drive Halfshafts

Summary

This Technical Bulletin has been issued for information only regarding the replacement of rear drive halfshafts.

Action

Modified rear drive halfshafts have been released to improve durability. The 'tubular' construction rear drive halfshaft has now been replaced by a 'solid bar' construction rear drive halfshaft. Should any N/A vehicle within the VIN ranges above, require replacement of the existing 'tubular' rear drive halfshaft, then a vehicle set of 'solid bar' rear drive halfshafts should be installed.